

3





PZ 1/2



8x (3,5 x 20)




4x (4 x 20)



4



„mm“



5



6 mm


PZ 1 / 2

4x (4,5 x 40)


4x


2x (4 x 30)

2x






6








8

A



i



Product improvement is a continuous process & specifications are subject to change without notice.  
© COPYRIGHT 2024 E&OE